



Terracon Soil Strata/Strength Values

Fyffe Ave Overcrossing NA SLOPE/W Analysis	
South Abutment 2-1 slope 33 ft - no seismic.gsz	
4/7/2020	1:260.37276




Terracon Soil Strata/Strength Values

Fyffe Ave Overcrossing NA SLOPE/W Analysis
South Abutment 2-1 slope 33 ft - seismic.gsz
4/7/2020
1:260.37276




Terracon Soil Strata/Strength Values

Fyffe Ave Overcrossing NA SLOPE/W Analysis	
North Abutment 2-1 slope 33 ft - no seismic.gsz	
4/7/2020	1:260



Terracon Soil Strata/Strength Values

Fyffe Ave Overcrossing NA SLOPE/W Analysis	
North Abutment 2-1 slope 33 ft - seismic.gsz	
4/7/2020	1:260




Twining Soil Strata/Strength Values

Fyffe Ave Overcrossing NA SLOPE/W Analysis

South Abutment 2-1 slope 33 ft - no seismic - Twining.gsz


4/8/2020

1:260




Twining Soil Strata/Strength Values

Fyffe Ave Overcrossing NA SLOPE/W Analysis	
South Abutment 2-1 slope 33 ft - seismic - Twining.gsz	
4/8/2020	1:260



Twining Soil Strata/Strength Values

Fyffe Ave Overcrossing NA SLOPE/W Analysis	
North Abutment 2-1 slope 33 ft - no seismic -Twining.gsz	
4/8/2020	1:260



Twining Soil Strata/Strength Values

Fyffe Ave Overcrossing NA SLOPE/W Analysis	
North Abutment 2-1 slope 33 ft - seismic -Twining.gsz	
4/8/2020	1:260