



1
S-4.1
BERTH SURFACE REPAIR PLAN 4
 SCALE: 1/8"=1'

LEGEND

- EX. CONC. TYP.
- EX. CLEAT
- EX. DECK CONC
- EX. UTILITY VAULT
- TYPE I REPAIR (BERTH SURFACE) SEE DETAILS 1, 2 AND 5 ON SHEET S-24.1.
- TYPE J REPAIR (TRAIN TRACKS). PATCH/FILL GROOVES AND GAPS TO ACHIEVE A FLAT WALKING SURFACE FOR THE ENTIRE LENGTH OF THE TRACK. MATCH EXISTING BERTH SURFACE GRADE. SEE DETAILS 1, 2 AND 4 ON SHEET S-24.1 (TYP. OF ALL).
- REMOVE NEW TREATED WOOD FENDERS (TYP. OF 4). SEE DETAILS 1 AND 2 ON SHEET S-24.1 AND PROJECT SPECIFICATIONS.
- FORM AND PATCH SLAB EDGE TO CREATE UNIFORM SLAB EDGE. FILL EXPANSION JOINT 2" DEEP WITH BACKER ROD AND FLEXIBLE SEALANT (700 PSI AFTER 16 DAYS OF CURING).



DILLON & MURPHY ENGINEERING
 847 N. CLUFF AVENUE
 SUITE A-2, LODI, CA 95240
 (209) 334-6613

PORT OF STOCKTON - EAST COMPLEX
 BERTH 7 & 8 FENDER REPLACEMENT & REPAIR PLANS

BERTH SURFACE REPAIR PLAN 4

STOCKTON, CALIFORNIA
 MARCH, 2022



REV. NO.	DESCRIPTION	DATE	SCALE: AS NOTED	BENCH MARK: 308 EL: 8.17
1	ADDENDUM NO. 1	5/16/2022	DRAWN BY: FA, JMC, NC	DESCRIPTION: DISC MARKING COS MONUMENT STAMPED "10S-2" IN MONUMENT WELL ON THE WEST SIDE OF TRAFFIC ISLAND AT NAVY DRIVE AND WASHINGTON STREET. (DATUM: NAVD88)
			DESIGNED BY: KM	SHEET S-4.1
			CHECKED BY: KM	9.1 OF 34
			AS BUILT BY:	JOB NO. 2107

S:\2021\2021\CONSTRUCTION ADMIN\2021\PORT OF STOCKTON - EAST COMPLEX\BERTH 7 & 8 FENDER REPLACEMENT & REPAIR PLANS\BERTH SURFACE REPAIR PLAN 4.dwg 16, 2022